DTSC 8022A (7/92) EPA 8700—22

Yellow: GENERATOR RETAINS

WORK ORDER

221 E. "D" ST. • P.O. Box 1175 WILMINGTON, CA 90748-1175 (310) 518-4700 • (800) 955-5359

WORK ORDER NO.

STOMER/ACCT. NO

10060

BILLING ADDRESS

SERVICE ADDRESS

DOUGLAS TORDANCE

			argin edit.	A CONTRACTOR OF THE PROPERTY OF	
ORDER DATE	DATE TO BE DONE	CUSTOMER P.O. #	ORDERED BY	TELEPHONE#	CONTACT PERSON
GREEN BAIL		Relate Weaher			
		27664-146080		100	
	DIV.#	DEPARTMENT	CUSTOMER'S EPA#	CUSTOMER'S BD OF EQUAL#	CONTACT PHONE #
REP.	DIV. #	DELTA IIII CIT			
				**	

Arrived at DAC Torrance 0745 Left DAC Torrance at 1115

DRIVER COMPLETE: SERVICES PERFORMED TANK 185 AN A H	pout Acid holden Aul to NERRIS	28 (2008) (1000) 20 (2008) 29 (2008) 4 (2008) 20 (2008) (2008) (2008) 2008)	
START 0700 STOP TIME	START / 5355 / END MILES	TRUCK / CORPORATION NUMBER	TRAILER 1 (00/47)
Manifest Number 93385635	Date Completed	ord bereby, the prevailing part	

In the event of any litigation arising out of this agreement or any transaction contemplated hereby, the prevailing party shall be entitled to reasonable attorney's fees, expenses and costs.

NOT AN INVOICE - BILLING WILL FOLLOW

Customer Signature, Polent D. Juelly, 06-17-

PRICING INSTRUCTIONS - DRUMS	REMINIO ARGINA	• • •
Clerical Hrs. 6	Per Hr.	W. Carlotte and Ca
Project Manager Hrs. ® SE	Per Hr	
9808 869 Fifait Y echinician <u>813 (010)</u> Hrs. ⊚	Per Hr.	
Second Technician Hrs. @	Per Hr.	CONTRACTOR NO
ON ABOUT Technician Hrs. @		
U.C., Fourth Technician Hrs. @		Property Digit
[설명하다] [18] [18] [18] [18] [18] [18] [18] [18	<u>as sous</u> Per Hr	<u> </u>
Truck # Hrs. @	그 그 경우 그리 왕이를 보고 있다. 이 시간 하루 배를 했다고 다	
Truck # Hrs. @		
Truck # Hrs, @	Per Hr.	· · · · · · · · · · · · · · · · · · ·
STINK OF THE STATE		Mental Composition of the State Section 1975
1 30 24 6 Moldays, Holldays, and After Hours @	**************************************	er og det er og
TRANSPORTATION & DISPOSAL FEES TO TSD FACILI		
5 Gal. Cans Liquid @	물이 그리는 그리와 뒤집을 그게 하고 하고 하는데 화목에 되었다. 중요하는 중요한	
5 Gal. Cans Solid @		
5 Gal. Cans Lab Packed @		
55 Gal. Drums Liquid @		
55 Gal. Drums Solid @	중 그들은 공기를 가능한다고 하나를 중심하는 하는 그를 맞았다고 밝혔다.	
55 Gal. Drums Lab Packed	스크는 그는 그들을 하면 하는 것이 되었다. 그는 그들은 사람이 되었다.	
Empty 5 Gal. Cans @	Each \	
Empty 55 Gal. Cans @	Each	
County Tax		
Transcore (Control of Control of		
MATERIALS USED		
5 Gal. Cans @	기보고 있다. 현기님 나는 아까지를 가는 제가 동호를 가고 있다.	
55 Gal. Drums @		
Recovery Drums @		
Bags (Other Describe) @		
Hazardous Waste Labels @	/ 1984 - B. J. B. H.	DRIVER COMPLETE
Drum Liners @		SERVICES PERFORMED I
Safety Equipment Number of Sets		and 12 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Saleth Edminitient unwiner or Sera		
PRICING INSTRUCTIONS - PUMPING ASSEMBLY	TRATE ANGES / STEEL STATE	STORE COOKS THAT
Compensation Hrs. @ \ \ \	\Per.Hr. aleG	123226 Procedural political
		- American
een of be Washout Fee, ying gollsverte ent yderent b	agreement or any hansaction contemplate	sid to too galana acceptifyas to tasks sid t
Dump Fee		onable attorney's leas, expenses and opers.
	ANTOT Customer Stensture, Z	FOT ANJINOPICE - BILLING WILL FOLLOW

3-1	Generator Name: Douglas Aircraft Co	EPA ID Number: <u>CAD086510005</u>				
•	Manifest Number: 85826 / 93385826	Date of Shipment: 6/17/94 .				
	Indicate Waste Line Item (11):					
	This notification is hereby submitted to <u>NORRIS ENVIRONMENTAL SERVICES</u> in compliance with EPA regulation described in 40 CFR Part 268 which prohibit the land disposal of certain hazardous wastes, unless these wastes are treat to meet specified standards or treated using specified treatment technologies.					
	I have marked the appropriate box(es) below, which indicates federal regulations.	how my waste must be managed to conform to land disposal ban and				
	California List Wastes Notification	RCRA Land Disposal Notification				
	Liquid hazardous waste including free liquids associated with any solid or sludge containing free cyanide at concentrations greater than or equal to 1000mg/L.					
	Treatment Standard-Cyanide Destruction Stabilization	I am the initial generator of an untreated waste identifications which must be treated in the appropriate treatment				
,	Liquid hazardous wastes, including free liquids associated with any solid or sludge, containing the following metals (or elements) at concentrations greater than or equal to those specified below:	standard set forth in 40 CFR 268 Subpart D, or where the treatment standard exists for the California List Waste, the waste must be treated to the levels specified under 40 CF 268.32.				
	Treatment Standard-Neutralization. Precipitation: Metals					
	Recovery					
	(check those that apply)	Waste Treated to Performance Standards				
	Arsenic and/or compounds (as As) Burium and/or compounds (as Ba) Cadmium and/or compounds (as Cd) Chromium (VI and/or compounds as Cr VI) Lead and/or compounds (as Pb) Mercury and/or compounds (as Rg) Selenium and/or compounds (as Se) Silver and/or compounds (as Ag) 5.0 mg/L: 0.2 mg/L: 1.0 mg/L: 5.0 mg/L: 5.0 mg/L: 5.0 mg/L: 5.0 mg/L: 5.0 mg/L: 5.0 mg/L:	The waste identified above has been treated in compliant with the applicable performance standars specified in 40 CFF 268 Subpart D and/or the applicable prohibitions set forth it 40 CFR 268.32. "I certify under penalty of law that I have personally examined and am familiar with the treatment technology and operation of the treatment process used to support this certification and that, based upon my inquiry of those individuals immediately responsible for obtaining this				
	Liquid bazardous wastes that are primarily water and contain halogenated organic compounds (HOCs) in total concentration greater than or equal to 1,000 mg/L and less than 10,000 mg/L HOCs (see attached listing of HOC constituents) Treatment Standard-Carbon Absorption Steam Stripping	information. I believe that the treatment process used to support this certification and that, based upon my inquiry of those individuals immediately responsible for obtaining this information. I believe that the treatment process has been operated and maintained properly so as to comply with the performance levels specified in 40 CFR Part 268 Subpart D and all applicable prohibitions set forth in 40 CFR 268.32 or RCRA Section 3004(s) without dilutions of the prohibited waste. I am aware that there are significant penalties for submitting a false certification, including the possibility of a fine and imprisonment.				
	Liquid hazardous wastes containing polychlorinated hiphenyls	Waste Subject to Variance				
	(PCBs) at concentrations greater than or equal to 50 ppm.					
	Treatment Standard-Incineration, high efficiency hoiler, other thermal treatment	m mm				
×	Liquid hazardous wastes having a pH less than or equal to two(2) or pH equal to or greater than 12.5.	The waste identified above is subject to a case-hy-case extension under 40 CFR 268.5, a no-migration petition under 40 CFR 268.6, a nationwide variance under Subpart C, or is				
	Treatment Standard-Neutralization Stabilization	soil or debris generated from a response action taken under CERCLA or corrective action under RCRA.				
۵	The spent solvent wastes specified in 40 CFR 261.31 as EPA Hazardous Wastes Nos F001, F002, F003, F004 and F005.					
	Treatment Standard-Specify technology used to meet Table CCWE Check constituent(s) on Table CCWE which were reduced below treatment standards					
Th th:	e most recent copy of waste analysis or a description of the know at all information submitted in this and all associated documents	viedge upon which this notification is based is attached. I hereby certify is complete and accurate to the best of my knowledge and information.				
	Robert G. Tuell, Jr.	Senior Plant Engineer 06/17/94 (310) 533-7926				

INITIAL ISOLATION PROTECTION TABLES FOR SELECTED HAZARDOUS MATERIALS

The table gives suggested distances for ISOLATING unprotected people from spill areas involving the hazardous materials shown, <u>IF THE LISTED MATERIAL IS NOT ON FIRE</u>. If the material is on fire, refer to the 2-digit Guide.

These materials were selected because their vapors have the potential to produce poisonous effects. The table is useful for no more than the first 30 minutes of an incident involving these materials. There are several good reasons for suggesting that the use of the table be limited specifically to the initial phase of a <u>no-fire</u> spill incident during transport.

D.O.T. EMERGENCY RESPONSE GUIDE 60

TABLE OF INITIAL ISOLATION AND PROTECTIVE ACTION DISTANCES

USE THIS TABLE WHEN THE MATERIAL IS NOT ON FIRE.

ID No.

SMALL SPILLS (Leak or spill from a small package or small leak from a large package.) LARGE SPILLS (Leak or spill from a large package or spill from many small packages.)

ATERIAL IS NOT ON FIRE.

NAME OF MATERIAL

First ISOLATE in all directions-(Feet) Then, PROTECT those persons in the DOWNWIND direction— (Miles) First, ISOLATE in all directions-(Feet) Then, PROTECT those persons in the DOWNWIND direction— (Miles)

No chemicals appear in Table of Isolation and Protective Action Distances which are assigned to this Guide number.

If the chemical name and ID Number the shipper entered on the front of this form match a name from this list, and NO FIRE exists, you must:


determine if the incident involves a small or large spill; look up the isolation distance; (Direct all person to move in a crosswind direction, away from the spill, to that distance.) look up the initial PROTECTIVE ACTION DISTANCE in the table. (For practical purposes, the Protective Action Zone is a square whose length and width are the same as the downwind distance shown in the table.)

WHEN APPROACHING THE SCENE OF AN ACCIDENT INVOLVING ANY CARGO (NOT ONLY REGULATED HAZARDOUS MATERIALS):

- APPROACH INCIDENT FROM AN UPWIND DIRECTION, IF POSSIBLE
- MOVE AND KEEP PEOPLE AWAY FROM INCIDENT SCENE
- DO NOT WALK INTO OR TOUCH ANY SPILLED MATERIAL
- AVOID INHALING FUMES, SMOKE AND VAPORS EVEN IF NO HAZARDOUS MATERIALS ARE INVOLVED
- DO NOT ASSUME THAT GASES OR VAPORS ARE HARMLESS BECAUSE OF LACK OF SMELL—ODORLESS GASES OR VAPORS MAY BE HARMFUL

As a first responder at the scene of a hazardous materials incident, seek additional and more specific information about any material in question as soon as possible. This Gulde Page is not intended for use during the cleanup phase for spilled materials, nor should it be used to determine compliance with any regulations. This information on this Emergency Response Form should be augmented by expert technical advice as soon as you have assessed the situation and have seen to the immediate needs of the people involved.

FOR FURTHER INFORMATION REFER TO DOT P 5800.5 (EMERGENCY RESPONSE GUIDEBOOK) AND TITLE 49 CODE OF FEDERAL REGULATIONS.



DOOR EVERENCY RESPONSE CUIDE GI

POTENTIAL HAZARDS

HEALTH HAZARDS

Contact causes burns to skin and eyes. If inhaled, may be harmful. Fire may produce irritating or poisonous gases. Runoff from fire control or dilution water may cause pollution.

FIRE OR EXPLOSION

Some of these materials may burn, but none of them ignites readily. Flammable/poisonous gases may accumulate in tanks and hopper cars. Some of these materials may ignite combustibles (wood, paper, oil, etc.)

EMERGENCY ACTION

Keep unnecessary people away; isolate hazard area and deny entry. Stay upwind; keep out of low areas. Positive pressure self-contained breathing apparatus (SCBA) and structural firefighters' protective clothing will provide limited protection. CALL CHEMTREC AT 1-800-424-9300 FOR EMERGENCY ASSISTANCE.

If water pollution occurs, notify the appropriate authorities.

FIRE

Some of these materials may react violently with water.

Small Fires: Dry chemical, CO2, water spray or regular foam.

Large Fires: Water spray, fog or regular foam.

Move container from fire area if you can do it without risk.

Apply cooling water to sides of containers that are exposed to flames until well after fire is out. Stay away from ends of tanks.

SPILL OR LEAK

Do not touch or walk through spilled material; stop leak if you can do it without risk. Small Spills: Take up with sand or other noncombustible absorbent

Small Spills: Take up with sand or other noncombustible absorber material and place into containers for later disposal.
Small Dry Spills: With clean shovel place material into clean, dry container and cover loosely; move containers from spill area.
Large Spills: Dike far ahead of liquid spill for later disposal.

FIRST AID

Move victim to fresh air; call emergency medical care.
In case of contact with material, immediately flush skin or eyes with running water for at least 15 minutes.

Remove and Isolate contaminated clothing and shoes at the site. Keep victim quiet and maintain normal body temperature.

Information on this Guide Page is from the 1990 Emergency Response Guidebook Dot P 5800.5. It applies only to the basic Description and Technical Name entered by the shipper at the top of this form.

Check to see whether the shipper commodity (Basic description entered at the top of this form) is listed by I.D.# and NAME OF THE MATERIAL in the Table of Initial Isolation and Protective Action Distances. This Table is partially reproduced on the back of this Guide Page to reflect only commodities assigned to this Guide Number. Use this information from the table in addition to the Guide Page IF THERE IS NO FIRE.

READ AND CHECK THE NAMES AND NUMBERS CAREFULLY BECAUSE COMPLETELY DIFFERENT HAZARDOUS MATERIALS CAN HAVE NAMES AND/OR NUMBERS WHICH ARE ALMOST THE SAME!

ERF 60 Printed by Labelmaster, An American Labelmark Co., Chicago, IL 60646 (800) 621-5805

	GROSS 45/00 P	TARE 33480 P	NETOGINIA 1, 620,	1500	DRUM CUUNI	GALLONS	DOCUMENT NUMBER: \$5826/93385826	A. a. can gray and gray as the state statements and the statements of the statement of the
WEIGHT TICKET		ā		lodine. 15		V	CUMENT	•
AN .	VENDOR: Laidlan	TRUCK #: 16039	DATE: 6-17-94	CONTENTS: Tank 185 - A	DISPOSAL FACILITY; Norris	DRIVER: Las Solud Torand	STATE MANIFEST DO	